

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER  
MISS  
44-COLUM  
24-

TOMBIGBEE RIVER BRIDGE

HAER No. MS-13

State Highway 182 spanning Tombigbee River  
Columbus  
Lowndes County  
Mississippi

J. Carlos Rosales, Photographer

April 1995

Note: 5" x 7" images were enlarge from 2" x 2" negatives

- MS-13-1      VIEW OF TOMBIGBEE RIVER BRIDGE FACING NORTHEAST. RIVER FLOW IS TO RIGHT. MUNICIPAL WATER TANK IS IN RIGHT BACKGROUND. MAIN SPAN IS IN FOREGROUND AND PONY SPANS ARE ON EITHER END.
  
- MS-13-2      VIEW OF TOMBIGBEE RIVER BRIDGE FACING SOUTHEAST. RIVER FLOW IS TO LEFT. SOUTH PONY SPAN IN BACKGROUND IS NOT CLEARLY SHOWN. NORTH PONY SPAN IS SHOWN ON THE LEFT OF MAIN SPAN.
  
- MS-13-3      VIEW OF TOMBIGBEE RIVER BRIDGE FACING NORTHEAST. NEW BRIDGE IS PARTIALLY SHOWN IN RIGHT BACKGROUND. RIVER FLOW IS TO RIGHT. NORTH PONY SPAN IS LEFT OF MAIN SPAN.
  
- MS-13-4      VIEW OF TOMBIGBEE RIVER BRIDGE FACING NORTHEAST. MUNICIPAL WATER TANK IS IN CENTER BACKGROUND. RIVER FLOW IS TO RIGHT.
  
- MS-13-5      VIEW OF TOMBIGBEE RIVER BRIDGE FACING EAST SHOWING SUPERSTRUCTURE OF SOUTH PONY SPAN. RIVER FLOW IS INTO PICTURE.
  
- MS-13-6      VIEW OF TOMBIGBEE RIVER BRIDGE FACING SOUTH ALONG CENTER OF ROADWAY SHOWING SUPERSTRUCTURE OF NORTH PONY SPAN AND MAIN SPAN. UTILITY LINES (ELECTRICAL AND TELEPHONE) ARE SHOWN ON RIGHT EDGE.
  
- MS-13-7      VIEW OF TOMBIGBEE RIVER BRIDGE FACING JUST RIGHT OF VIEW SHOWN IN PHOTOGRAPH No. MS-13-6. NEW BRIDGE IS PARTIALLY SHOWN IN THE BACKGROUND.
  
- MS-13-8      VIEW OF TOMBIGBEE RIVER BRIDGE FACING JUST RIGHT OF VIEW SHOWN IN PHOTOGRAPH No. MS-13-7. NEW BRIDGE IS PARTIALLY SHOWN IN THE BACKGROUND.
  
- MS-13-9      VIEW OF TOMBIGBEE RIVER BRIDGE FACING SOUTHEAST SHOWING DETAILS OF SUPERSTRUCTURE ON NORTH PONY SPAN ON DOWNSTREAM SIDE OF BRIDGE. RAILING SHOWN ON MAIN SPAN IS NOT PART OF ORIGINAL STRUCTURE. ORIGINAL RAILING HAS BEEN REPLACED WITH MODERN GUARD RAIL W-BEAMS BY MAINTENANCE PERSONNEL.

**TOMBIGBEE RIVER BRIDGE  
HAER No. MS-13 (Page 2)  
INDEX TO PHOTOGRAPHS**

- MS-13-10** VIEW OF TOMBIGBEE RIVER BRIDGE FACING NORTHEAST SHOWING DAMAGE TO RAILING ON DOWNSTREAM SIDE OF NORTH PONY SPAN. THIS VIEW IS JUST NORTH OF VIEW SHOWN IN PHOTOGRAPH No. MS-13-9.
- MS-13-11** VIEW OF TOMBIGBEE RIVER BRIDGE FACING NORTHEAST ALONG CENTER OF ROADWAY. NORTH PONY SPAN IS IN BACKGROUND CENTER AND NEW BRIDGE IS PARTIALLY SHOWN IN BACKGROUND LEFT. BARRELS SHOWN ARE REMNANTS OF TRAFFIC CONTROL DEVICES USED FOR ONE LANE TRAFFIC DUE TO REDUCED WEIGHT CAPACITY OF BRIDGE BEFORE CLOSURE.
- MS-13-12** VIEW OF TOMBIGBEE RIVER BRIDGE FACING SOUTHWEST THROUGH THE NORTHERN PORTION OF THE MAIN SPAN. THE NEW BRIDGE IS PARTIALLY SHOWN IN THE BACKGROUND. RIVER FLOW IS TO THE LEFT.
- MS-13-13** VIEW OF TOMBIGBEE RIVER BRIDGE FACING SOUTH ALONG THE PEDESTRIAN WALKWAY. NORTH PONY SPAN IS IN FOREGROUND AND MAIN SPAN IS IN CENTER BACKGROUND. THE NEW BRIDGE IS PARTIALLY SHOWN IN RIGHT BACKGROUND. RIVER FLOW IS TO THE LEFT.
- MS-13-14** VIEW OF TOMBIGBEE RIVER BRIDGE NORTH ALONG CENTER OF ROADWAY. THE BARRICADES IN THE MIDDLE OF THE BRIDGE ARE TO PREVENT PEDESTRIAN AND VEHICULAR TRAFFIC.
- MS-13-15** VIEW OF TOMBIGBEE RIVER BRIDGE FACING SAME DIRECTION AS IN PHOTOGRAPH No. MS-13-14 EXCEPT THIS VIEW IS THE UNDERSIDE OF THE BRIDGE.
- MS-13-16** VIEW OF TOMBIGBEE RIVER BRIDGE FACING EAST JUST SOUTH OF NORTH END OF BRIDGE. THE EXISTING CONCRETE RAILING IS BROKEN.
- MS-13-17** VIEW OF TOMBIGBEE RIVER BRIDGE SHOWING SAME BROKEN RAILING AS WAS SHOWN IN PHOTOGRAPH No. MS-13-16. VIEW IS FROM THE GROUND LOOKING NORTHWEST.
- MS-13-18** VIEW OF TOMBIGBEE RIVER BRIDGE FACING EAST SHOWING UPSTREAM SIDE OF BRIDGE OPPOSITE BROKEN RAILING LOCATED ON THE DOWNSTREAM SIDE. FALLEN POWER POLE AND TELEPHONE CABLE IS SHOWN IN THE CENTER OF THE PHOTOGRAPH.
- MS-13-19** VIEW OF TOMBIGBEE RIVER BRIDGE FACING NORTHEAST FROM SAME LOCATION AS PHOTOGRAPH No. MS-13-19

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER  
MISS  
44-COLUM  
24-

TOMBIGBEE RIVER BRIDGE

HAER No. MS-13

State Highway 182 spanning Tombigbee River  
Columbus  
Lowndes County  
Mississippi

J. Carlos Rosales, Photographer

April 1995

Note: 5" x 7" images were enlarge from 2" x 2" negatives

- MS-13-1      VIEW OF TOMBIGBEE RIVER BRIDGE FACING NORTHEAST. RIVER FLOW IS TO RIGHT. MUNICIPAL WATER TANK IS IN RIGHT BACKGROUND. MAIN SPAN IS IN FOREGROUND AND PONY SPANS ARE ON EITHER END.
- MS-13-2      VIEW OF TOMBIGBEE RIVER BRIDGE FACING SOUTHEAST. RIVER FLOW IS TO LEFT. SOUTH PONY SPAN IN BACKGROUND IS NOT CLEARLY SHOWN. NORTH PONY SPAN IS SHOWN ON THE LEFT OF MAIN SPAN.
- MS-13-3      VIEW OF TOMBIGBEE RIVER BRIDGE FACING NORTHEAST. NEW BRIDGE IS PARTIALLY SHOWN IN RIGHT BACKGROUND. RIVER FLOW IS TO RIGHT. NORTH PONY SPAN IS LEFT OF MAIN SPAN.
- MS-13-4      VIEW OF TOMBIGBEE RIVER BRIDGE FACING NORTHEAST. MUNICIPAL WATER TANK IS IN CENTER BACKGROUND. RIVER FLOW IS TO RIGHT.
- MS-13-5      VIEW OF TOMBIGBEE RIVER BRIDGE FACING EAST SHOWING SUPERSTRUCTURE OF SOUTH PONY SPAN. RIVER FLOW IS INTO PICTURE.
- MS-13-6      VIEW OF TOMBIGBEE RIVER BRIDGE FACING SOUTH ALONG CENTER OF ROADWAY SHOWING SUPERSTRUCTURE OF NORTH PONY SPAN AND MAIN SPAN. UTILITY LINES (ELECTRICAL AND TELEPHONE) ARE SHOWN ON RIGHT EDGE.
- MS-13-7      VIEW OF TOMBIGBEE RIVER BRIDGE FACING JUST RIGHT OF VIEW SHOWN IN PHOTOGRAPH No. MS-13-6. NEW BRIDGE IS PARTIALLY SHOWN IN THE BACKGROUND.
- MS-13-8      VIEW OF TOMBIGBEE RIVER BRIDGE FACING JUST RIGHT OF VIEW SHOWN IN PHOTOGRAPH No. MS-13-7. NEW BRIDGE IS PARTIALLY SHOWN IN THE BACKGROUND.
- MS-13-9      VIEW OF TOMBIGBEE RIVER BRIDGE FACING SOUTHEAST SHOWING DETAILS OF SUPERSTRUCTURE ON NORTH PONY SPAN ON DOWNSTREAM SIDE OF BRIDGE. RAILING SHOWN ON MAIN SPAN IS NOT PART OF ORIGINAL STRUCTURE. ORIGINAL RAILING HAS BEEN REPLACED WITH MODERN GUARD RAIL W-BEAMS BY MAINTENANCE PERSONNEL.

**TOMBIGBEE RIVER BRIDGE  
HAER No. MS-13 (Page 2)  
INDEX TO PHOTOGRAPHS**

- MS-13-10** VIEW OF TOMBIGBEE RIVER BRIDGE FACING NORTHEAST SHOWING DAMAGE TO RAILING ON DOWNSTREAM SIDE OF NORTH PONY SPAN. THIS VIEW IS JUST NORTH OF VIEW SHOWN IN PHOTOGRAPH No. MS-13-9.
- MS-13-11** VIEW OF TOMBIGBEE RIVER BRIDGE FACING NORTHEAST ALONG CENTER OF ROADWAY. NORTH PONY SPAN IS IN BACKGROUND CENTER AND NEW BRIDGE IS PARTIALLY SHOWN IN BACKGROUND LEFT. BARRELS SHOWN ARE REMNANTS OF TRAFFIC CONTROL DEVICES USED FOR ONE LANE TRAFFIC DUE TO REDUCED WEIGHT CAPACITY OF BRIDGE BEFORE CLOSURE.
- MS-13-12** VIEW OF TOMBIGBEE RIVER BRIDGE FACING SOUTHWEST THROUGH THE NORTHERN PORTION OF THE MAIN SPAN. THE NEW BRIDGE IS PARTIALLY SHOWN IN THE BACKGROUND. RIVER FLOW IS TO THE LEFT.
- MS-13-13** VIEW OF TOMBIGBEE RIVER BRIDGE FACING SOUTH ALONG THE PEDESTRIAN WALKWAY. NORTH PONY SPAN IS IN FOREGROUND AND MAIN SPAN IS IN CENTER BACKGROUND. THE NEW BRIDGE IS PARTIALLY SHOWN IN RIGHT BACKGROUND. RIVER FLOW IS TO THE LEFT.
- MS-13-14** VIEW OF TOMBIGBEE RIVER BRIDGE NORTH ALONG CENTER OF ROADWAY. THE BARRICADES IN THE MIDDLE OF THE BRIDGE ARE TO PREVENT PEDESTRIAN AND VEHICULAR TRAFFIC.
- MS-13-15** VIEW OF TOMBIGBEE RIVER BRIDGE FACING SAME DIRECTION AS IN PHOTOGRAPH No. MS-13-14 EXCEPT THIS VIEW IS THE UNDERSIDE OF THE BRIDGE.
- MS-13-16** VIEW OF TOMBIGBEE RIVER BRIDGE FACING EAST JUST SOUTH OF NORTH END OF BRIDGE. THE EXISTING CONCRETE RAILING IS BROKEN.
- MS-13-17** VIEW OF TOMBIGBEE RIVER BRIDGE SHOWING SAME BROKEN RAILING AS WAS SHOWN IN PHOTOGRAPH No. MS-13-16. VIEW IS FROM THE GROUND LOOKING NORTHWEST.
- MS-13-18** VIEW OF TOMBIGBEE RIVER BRIDGE FACING EAST SHOWING UPSTREAM SIDE OF BRIDGE OPPOSITE BROKEN RAILING LOCATED ON THE DOWNSTREAM SIDE. FALLEN POWER POLE AND TELEPHONE CABLE IS SHOWN IN THE CENTER OF THE PHOTOGRAPH.
- MS-13-19** VIEW OF TOMBIGBEE RIVER BRIDGE FACING NORTHEAST FROM SAME LOCATION AS PHOTOGRAPH No. MS-13-19